Record of officer decision

Decision title:	To approve the expenditure of up to £48k for planned maintenance re-roofing at Madley Primary School from school capital maintenance funding
Date of decision:	13 June 2019
Decision maker:	Assistant Director Education Development and Skills
Authority for delegated decision:	The authority for the specified officer to take this decision is set out in the cabinet report approved 17 January 2019 (http://hc-modgov:9070/ieDecisionDetails.aspx?ID=5593)
Ward:	Stoney Street
Consultation:	Cabinet debated and approved a report on the 2019/20 Local Authority Schools Maintenance Programme on 17 January 2019. Consultation has already been done in respect of the overall
	programme with the Capital Strategy Consultative Group, comprising a number of headteachers and council officers, who agreed the programme as a constructive way forward for the use of the grant.
	Political groups were consulted on the programme and no objections or comments were received.
Decision made:	Agreement to: • To approve the re-roofing planned maintenance works at Madley Primary School, to be undertaken via Balfour Beatty Living Places, at an initial cost of £41,556 plus associated contingency, professional and statutory fees. A total cost up to the value of £48,000
	 Fund the works from the existing school capital maintenance budget
Reasons for decision:	Madley was included in the approved schools planned maintenance programme 2019/20 for roofing works.
	The costs for the works will be covered using £48,000 from the schools capital maintenance budget; £27,500 of which has already been approved for expenditure against this item, the remaining £20,500 will be funded from the contingency within the schools capital maintenance budget.

Highlight any associated risks/finance/legal/equality considerations:	The works can be covered within the budget originally allocated for roofing as part of the planned maintenance programme plus some funding from the contingency within the schools capital maintenance budget.
	There is a risk that once on site, further work is identified if the condition of the existing roof structure is found to be poor. A contingency has been allowed to cover unforeseen elements once the existing roof covering has been removed. Should this contingency be insufficient than a further officer decision will be required.
•	Do nothing. This is not recommended as the roof is in poor condition allowing water into the building disrupting services and causing further deterioration to the building fabric leading to greater reactive costs.
	Undertake localized patch repairs. This is not recommended as it will not provide a comprehensive resolution to the problem and may lead to greater deterioration of the roof in the longer term.
Details of any declarations of interest made:	None

Signed Date: 13 June 2019