## **Record of officer decision**

Decision title:	To approve the expenditure of up to £7k for planned maintenance switchgear replacement at Luston Primary School from school capital maintenance funding
Date of decision:	12 July 2019
Decision maker:	Assistant Director Education Development and Skills
Authority for delegated decision:	The authority for the specified officer to take this decision is set out in the cabinet report approved 17 January 2019 ( <a href="http://hc-modgov:9070/ieDecisionDetails.aspx?ID=5593">http://hc-modgov:9070/ieDecisionDetails.aspx?ID=5593</a> )
Ward:	Bircher
Consultation:	Cabinet debated and approved a report on the 2019/20 Local Authority Schools Maintenance Programme on 17 January 2019.  Consultation has already been done in respect of the overall programme with the Capital Strategy Consultative Group, comprising a number of headteachers and council officers, who agreed the programme as a constructive way forward for the use of the grant.  Political groups were consulted on the programme and no objections or comments were received.
Decision made:	<ul> <li>Agreement to:         <ul> <li>To approve the switchgear replacement planned maintenance works at Luston Primary School, to be undertaken via Balfour Beatty Living Places, at an initial cost of £4,508 plus associated contingency, professional and statutory fees. A total cost up to the value of £7,000</li> </ul> </li> <li>Fund the works from the existing school capital maintenance budget</li> </ul>
Reasons for decision:	Luston Primary was included in the approved schools planned maintenance programme 2019/20 for switchgear replacement works.  The costs received lie within the original budget provided in the cabinet report of £15k plus fees.

Highlight any associated risks/finance/legal/equality considerations:	The works can be covered within the budget originally allocated for switchgear as part of the planned maintenance programme.  There is a risk that once on site, further work is identified if the condition of the supporting and surrounding infrastructures are found to be poor. A contingency has been allowed to cover unforeseen elements once the works are commenced. Should this contingency be insufficient then a further officer decision will be required.
Details of any alternative options considered and rejected:	Do nothing. This is not recommended as the switchgear has reached the end of its life expectancy. Not undertaking the works could result in a significant health & safety risk to the building and its occupants.  Undertake a different set of switchgear replacement works. The works put forward are considered the most appropriate and necessary to ensure the safety of the building and its occupants.
Details of any declarations of interest made:	None
of filterest filade.	

Signed Date: 12/07/2019