Record of officer decision

Decision title:	To approve the expenditure of up to £15k for
	urgent damp repairs at Kington Primary School
	from school capital maintenance funding
Date of decision:	8 April 2019
Decision maker:	Interim Education & Capital Manager
Authority for delegated	The authority for the specified officer to take this decision is set out
decision:	in the cabinet report approved 28 June 2018 (http://hc-modgov:9070/ieDecisionDetails.aspx?ID=5189)
Ward:	Kington
Consultation:	None
Decision made:	Agreement to:
Reasons for decision:	Kington Primary has been included in the planned maintenance programme 2018/19 for heating works. At the time of the site visit the school highlighted that there was some damp in one of the classrooms, an office and a hallway. A survey was arranged to assess the extent and type of damp with a view to undertaking remedial action to address any issues found. The survey noted in all areas inspected that there is visible evidence of dampness to the walls which appear to be a combination of rising dampness due to the lack of an effective damp proof course and also that of hygroscopic salt contamination. The survey provided a recommended course of action.
	The school has taken immediate action by placing cupboards in front of the affected area in the classroom preventing children from being in its immediate vicinity. The cost of the damp proofing will be added to the maintenance programme for 2018/19 and funded from the contingency within the existing school capital maintenance budget.
Highlight any associated risks/finance/legal/equality considerations:	The estimated costs of the emergency works are £12,671 plus associated contingency, professional and associated fees. A total cost up to the value of £15k. This will be funded from the contingency within the school capital maintenance budget.
	Contingency at start of year £193k Spend to date £175k Peterchurch re-roofing £15k Remaining contingency £3k A potential risk is that on the removal of fixtures in the rooms other

	problems may come to light, such as damp penetration further than identified in the report as this only concentrated on the areas with noticeable damp. If this is the case a further officer decision could be required.
options considered and rejected:	Do nothing. This is not recommended as the risk of these works not being completed means that parts of the school site will become unsightly, unusable and pose a health and safety risk to children, staff and visitors to the school.
Details of any declarations of interest made:	None

Signed: Date: 8 April 2019